

賀茂環境衛生センター解体工事に係る粉じん測定結果

令和5年度

A(3号炉集じん器) B(1・2号炉集じん器)

(単位:cpm)

	4月		5月		6月		7月		8月		9月		10月		11月		12月		1月		2月		3月	
	A	B	A	B	A	B	A	B	A	B	A	B	A	B	A	B	A	B	A	B	A	B	A	B
1	/	/	/	/	/	0	/	0	1	1	1	0	/	/	1	1	/	/	/	/	/	/	/	/
2	/	/	/	/	/	1	/	/	1	1	0	0	0	0	1	1	/	/	/	/	/	/	/	/
3	/	/	/	/	/	0	/	0	1	0	/	/	0	0	1	1	/	/	/	/	/	/	/	/
4	/	/	/	/	/	/	/	0	1	1	0	0	0	0	1	0	/	/	/	/	/	/	/	/
5	/	/	/	/	/	0	/	0	2	0	0	0	0	1	/	/	/	/	/	/	/	/	/	/
6	/	/	/	/	/	0	/	0	/	/	1	0	1	1	1	1	/	/	/	/	/	/	/	/
7	/	/	/	/	/	1	/	0	1	1	0	0	0	1	1	1	/	/	/	/	/	/	/	/
8	/	/	/	/	/	1	/	0	0	2	0	0	/	/	1	0	/	/	/	/	/	/	/	/
9	/	/	/	/	/	1	/	/	1	1	0	1	0	0	1	0	/	/	/	/	/	/	/	/
10	/	/	/	/	/	0	/	1	0	0	/	/	1	0	1	1	/	/	/	/	/	/	/	/
11	/	/	/	/	/	/	/	0	/	/	2	0	1	0	/	/	/	/	/	/	/	/	/	/
12	/	/	/	/	/	0	/	0	/	/	0	0	0	0	/	/	/	/	/	/	/	/	/	/
13	/	/	/	/	/	0	/	0	/	/	0	1	0	0	1	1	/	/	/	/	/	/	/	/
14	/	/	/	/	/	0	/	0	/	/	1	0	1	0	1	1	/	/	/	/	/	/	/	/
15	/	/	/	/	/	1	/	0	/	/	0	0	/	/	1	0	/	/	/	/	/	/	/	/
16	/	/	/	/	/	1	/	/	1	2	1	1	1	0	1	0	/	/	/	/	/	/	/	/
17	/	/	/	/	/	0	/	0	2	2	/	/	1	1	1	1	/	/	/	/	/	/	/	/
18	/	/	/	/	/	/	/	0	0	2	0	0	0	1	1	0	/	/	/	/	/	/	/	/
19	/	/	/	/	/	0	/	0	0	0	0	0	1	1	/	/	/	/	/	/	/	/	/	/
20	/	/	/	/	/	0	/	0	/	/	1	0	1	1	/	/	/	/	/	/	/	/	/	/
21	/	/	/	/	/	0	/	0	0	0	1	0	0	1	/	/	/	/	/	/	/	/	/	/
22	/	/	/	/	/	1	/	0	0	0	0	0	/	/	/	/	/	/	/	/	/	/	/	/
23	/	/	/	/	/	0	/	0	0	0	0	1	1	0	/	/	/	/	/	/	/	/	/	/
24	/	/	/	/	/	0	/	0	0	0	/	/	1	1	/	/	/	/	/	/	/	/	/	/
25	/	/	/	0	/	0	0	0	0	0	0	0	1	0	/	/	/	/	/	/	/	/	/	/
26	/	/	/	0	/	0	1	0	1	0	0	0	1	1	/	/	/	/	/	/	/	/	/	/
27	/	/	/	0	/	0	0	0	/	/	0	1	1	1	/	/	/	/	/	/	/	/	/	/
28	/	/	/	0	/	0	1	0	0	1	0	0	1	0	/	/	/	/	/	/	/	/	/	/
29	/	/	/	0	/	0	0	0	0	1	0	0	/	/	/	/	/	/	/	/	/	/	/	/
30	/	/	/	0	/	0	0	/	1	0	0	1	1	0	/	/	/	/	/	/	/	/	/	/
31	/	/	/	0	/	1	0	0	1	/	/	1	1	/	/	/	/	/	/	/	/	/	/	/

※排出基準値は132cpmとしています。